

## 9718 MEN'S SOFT SHELL JACKET

### MEN'S SIZES S-5XL

- :: Cutting edge soft shell fabric provides wind/water-resistance & breathability
- :: Soft shell bonded to microfleece lining for added warmth
- :: Also available in Women's sizes, style 5718

Wind flap & chin guard provides added protection

Stand-up collar



Zippered mini pocket on sleeve

Zippered side and inside valuables pocket for secured storage

Open hem with adjustable shockcord drawstring and cord locks

Open cuffs with Velcro™

**COMFORT & CONVENIENCE**

- :: Hi-Tech 3-layer poly/spandex and microfleece bonded with a special middle laminate layer for added warmth
- :: Non-bulky fit for ease of movement and added comfort
- :: Breathable and weather-resistant
- :: Microfleece-lined pockets for comfort
- :: Wind flap provides enhanced wind/rain protection
- :: Chin guard protects against chafing on the neck and face
- :: Side pocket zippers close upward to protect contents from falling out
- :: Suitable as corporate, fall and winter, every day, and team wear
- :: Women's companion style 5718

**FABRIC**

90% polyester/10% spandex bonded to 100% polyester microfleece (10.18 oz/yd<sup>2</sup>, 345 gsm)

**SIZES**

Men's Sizes S-5XL

**COLORS**

040 Navy/Vapor Grey, 106 Black/Vapor Grey, 247 Midnight Blue/Black

**GARMENT CARE**

Machine wash cold gentle cycle with like colors. Line dry. Do not use chlorine bleach. Do not use fabric softeners. Low iron with press cloth.

**DECORATION RECOMMENDATIONS**

Embroidery: Ballpoint 75/10 needle. Tearaway backings. No topical solvent needed.

Heat Transfer: Max heat recommended is 305°F

Screen Printing: Please test for dye migration as it may occur 24 hours later. Automatic printing process is recommended. Maximum number of colors recommended is 2. Ink Recommendations: Poly Low Bleed for white inks and Plastisol for dark inks. Catalyst recommended. Dryer temperature should not exceed 305°F.

040 NAVY

106 BLACK  
+VAPOR  
GREY

247 MIDNIGHT  
BLUE  
+BLACK

SOFT SHELL JACKET MEN'S 9718	S	M	L	XL	2XL	3XL	4XL	5XL	TOLERANCE
<b>BODY LENGTH</b> measure from neck (CB neck)	26	27	28	29	30	31	31 ½	32	½ +/-
<b>CHEST WIDTH</b> 1 inch below armhole	22	23	24	26	28	30	31	33	½ +/-
<b>BOTTOM OPENING WIDTH RELAXED 1/2</b>	21 ½	22 ½	23 ½	25 ½	27 ½	29 ½	20 ½	22 ½	½ +/-
<b>SLEEVE LENGTH FROM CB</b> short	34	35	36	36 ½	37	37 ½	38	38 ¾	½ +/-

**KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)**

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED